

Virtual COM Port Instruction

一、Update Bluetooth Receive:

1, Plug the Bluetooth Receive to PC

2, Decompression the document of XB-COM

V3.2.07-395M-20141126 , and open the DFU XB RFR-COM

V3.2.07-395M.exe, then click the key of “Upgrade”, then it will upload ,when upload finished, close this software

二、Update Virtual COM Port software


1. Open the “Device Management” of PC, (Right-hand button “ Compute ” → choose “Attribute” → choose “ Device Management”)

2. There will a Cannot recognize drive of “XB USB EasyCOM” under “Other equipment”, choose it ,and click “right-hand button” →choose “Upload Software of Drive” →choose “Find the Software from the computer” →choose “Browse” →find “Next Step” →if it pop a dialog box of “Windows Safe”, then choose “Install this Drive from Beginning to End ” → Update succeed or fail it will a prompt message, if update Fail, update again, if succeed, close the dialog box.

3. When update succeed ,there will a serial port “XB USB EasyCOM(COMx)” under “COM and LPT” of “Device Management” of PC, “X” represents the serial port

三, Pair the scanner with the Bluetooth :

Pair the scanner according to the manual, when paired succeed, the indicator light will become purple

四, Open the debug software “ XCOM V2.0.exe”, and set it, then scan any data barcode to test the scanner if it OK